



















Parts List				
 10120 Lifting Crane  x1	 10452 3" Clamp Pair  x2	 10407 Gasket  x4	 6005 Lifting Tackle  x1	 10121 Ferrule Plate  x2
 60120 R-Clip  x1	 60621 M6 x 20mm Bolt  x4	 60702 Nylon Washer  x8		
 60665 4.8 x 16 Rivet  x8	 60060 M6 Nylock Nut  x4	 60068 Nut Covers  x8		

Tools Required	
 2 x 10mm Spanners	 Rivet Gun
 Ø 5mm (3/16") Drill Bit	 Measuring Tool





UK & International  
+44 (0)1392531280  
sales@scanstrut.com

For further installation  
and warranty information  
please visit:  
www.scanstrut.com

USA  
+1 860 308 1416  
usasales@scanstrut.com

**SCANSTRUT**



Share your installation with us.



UK & International  
+44 (0)1392531280  
sales@scanstrut.com

For further installation  
and warranty information  
please visit:  
www.scanstrut.com

USA  
+1 860 308 1416  
usasales@scanstrut.com

**SCANSTRUT®**